




- TO: Greenheck International Representatives
- FROM: Mukul Sharma Product Manager, India
- DATE: September 25, 2024
- SUBJECT: CAPS®: Model RA Airflow Direction



In the recent CAPS<sup>®</sup> 4.45 release, the airflow direction for the model RA is displayed as flowing from the motor to the impeller, as highlighted in the screenshot below.

The correct airflow direction should be from the impeller to the motor. This issue has been reported and will be corrected in the next CAPS release.



We appreciate your understanding in this regard.

If you need further information, contact the GIN application team at <u>gin.application@greenheck.com</u> with a copy sent to <u>gin.service@greenheck.com</u>.

## Mukul Sharma